

S.No	Particular	Per sft (RS)
1	Pressing+cutting+edge banding (0.5 tape)	40
2	Pressing+cutting+edge banding (2mm tape)	50
3	Pressing+cutting+edge banding (1.5 mm glass tape)	55
4	Pressing+cutting+edge banding (2 mm glass tape)	58
5	Cutting+edge banding (without edge banding)	20
6	Cutting only	10
7	Pressing only one side (include fevicol paste)	250
8	Pressing only two side (include fevicol paste)	500
9	Pressing only one side (Without fevicol paste)	100
10	Pressing only two side (Without fevicol paste)	150
11	Cutting+edge banding (include tape 2mm)	35
12	Cutting+edge banding (include tape 0.5mm)	29
13	Edge banding only (without tape)	10
14	Glass cutout (Small door)	150
15	Glass cutout (Big door)	250
16	0.65 or 0.8 tape	45
17	CNC as per Design charge	